EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	2	("5837388").PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:23
L2	6	(("4923100") or ("20060027625") or ("20030085258")).PN.	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	OFF .	2006/12/01 10:31
L3	0	(1 or 2) and sinter\$4	US-PGPUB; USPAT; USOCR; FPRS; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:32
L4	7054	((228/56.3) or (428/650,654,655, 680) or (148/426,432,437,451, 523) or (420/441,469,499,528, 548)).CCLS.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:35
L5	10549	(braze or braz\$4 or solder or solder\$4 or filler) near (sheet or foil or insert or tape)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:38
L6	10549 ,	(4 or 5) and (braze or braz\$4 or solder or solder\$4 or filler) near (sheet or foil or insert or tape)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	OFF	2006/12/01 10:38
L10	12518	(braze or braz\$4 or solder or solder\$4 or filler) near (sheet or foil or insert or tape)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2006/12/01 10:38

EAST Search History

			1	ı — — — — — — — — — — — — — — — — — — —	I	
L12	12518	(4 or 10) and (braze or braz\$4 or solder or solder\$4 or filler) near (sheet or foil or insert or tape)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:38
L13	670	12 and powder near (filler or metal or mix or mixture or mix\$4 or compact\$4 or compaction)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:39
L14	325	13 and powder near (mix or mixture or mix\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:40
L15	31	14 and powder near (press\$4 or compact\$4 or roll adj compact\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:41
L18	8	15 and (ni or nickel) near (braze or braz\$4 or solder or solder\$4 or filler or powder)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:43
L19	13	15 and ("al" or aluminum) near (braze or braz\$4 or solder or solder\$4 or filler or powder)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:43
L20	11	19 and ("si" or silicon) near ("al" or aluminum or braze or braz\$4 or solder or solder\$4 or filler or powder)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2006/12/01 10:44
L21	10	15 and (cu or copper) near (braze or braz\$4 or solder or solder\$4 or filler or sheet or foil or powder or filler)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:44

EAST Search History

L22	3	21 and ("p" or phosphorous) near (cu or copper or braze or braz\$4 or solder or solder\$4 or filler or sheet or foil or powder or filler)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2006/12/01 10:47
L23	1	15 and powder near (roll and compact\$4)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON .	2006/12/01 10:47